


22027

ILS RWY 18R (CAT II)
HUNTSVILLE INTL-CARL T JONES FLD (HSV)


ALSF-2

MISSED APPROACH: Climb to 1300 then climbing right turn to 3000 on heading 270° and RQZ R-230 to JUVLO/RQZ 28.7 DME and hold.

[illegible]

CATEGORY	A	B	C	D
S-ILS 18R	RA 105/12 100 DA 729			

CATEGORY II ILS - SPECIAL AIRCREW
& AIRCRAFT CERTIFICATION REQUIRED



TDZ/CL Rwy 18R and 36L
HIRL Rwy 18L-36R and 18R-36L **L**

HUNTSVILLE INTL-CARL T JONES FLD (HSV)
34°38'N-86°47'W ILS RWY 18R (CAT II)