

|                                                      |                        |                                                                |
|------------------------------------------------------|------------------------|----------------------------------------------------------------|
| LOC/DME I-IND<br><b>111.75</b><br>Chan <b>54</b> (Y) | APP CRS<br><b>050°</b> | Rwy Idg <b>11200</b><br>TDZE <b>747</b><br>Apt Elev <b>796</b> |
|------------------------------------------------------|------------------------|----------------------------------------------------------------|

ILS RWY 5L (CAT II & III)

INDIANAPOLIS INTL (IND)

⚠

Simultaneous approach authorized.  
CAT III: Localizer not suitable for electronic rollout guidance. DME or RADAR required.

ALSf-2

MISSED APPROACH: Climb to 1700 then climbing left turn to 3000 direct VHP VORTAC then on VHP VORTAC R-303 to KEADY/VHP 4.9 DME/RADAR and hold.

|                         |                                              |                                  |                         |                                 |       |
|-------------------------|----------------------------------------------|----------------------------------|-------------------------|---------------------------------|-------|
| D-ATIS<br><b>134.25</b> | INDIANAPOLIS APP CON<br><b>128.175 317.8</b> | INDY TOWER<br><b>120.9 257.8</b> | GND CON<br><b>121.9</b> | CLNC DEL<br><b>128.75 257.8</b> | CPDLC |
|-------------------------|----------------------------------------------|----------------------------------|-------------------------|---------------------------------|-------|

